



| ARTICOLO | Ø1 | A | B |
|----------|--------|----|----|
| 4100 12 | G1/2 | 14 | 25 |
| 4100 34 | G3/4 | 14 | 30 |
| 4100 1 | G1 | 16 | 37 |
| 4100 114 | G1 1/4 | 18 | 47 |
| 4100 112 | G1 1/2 | 19 | 54 |

Quote espresse in mm